



Worldwide repairs carried out with PolymerMetal®

REP-#146



At a steelwork, heavy erosion caused damage of a blast furnace. Several areas of the conveyer cone were severely damaged due to the continuous loading with coke. Some plates were welded on the cone and then coated with Ceramium as well as some other damaged parts and the machine was put into operation successfully again.

MultiMetall
the MetalExistenceCompany®