



Worldwide repairs carried out with PolymerMetal®

REP-# 061



A leakage at the stern of a barge was sealed under water using MM-metal UW with Hardener UW9. The repair was completed within 30 minutes time.

MultiMetal
the MetalExistenceCompany®