



Worldwide repairs carried out with PolymerMetal®

REP-# 081



Leakages (micro pores) in a cylinder head were closed with Sealium.

MultiMetall
the MetalExistenceCompany®