




Worldwide repairs carried out with PolymerMetal®

REP-# 113



Repair of gas drilling surge valves. Abrasion due to escaping gas (2800 psi) and carrying contaminations such as e.g. sand. The repair has been carried out using Ceramium. A later inspection did not reveal any damages.

**MultiMetal**  
the MetalExistenceCompany®